

## BELZONA SEALS UNSANITARY LEAKING FLOOR DRAIN IN FOOD PLANT

### CUSTOMER

Pet food manufacturer, O'Fallon, MO

### APPLICATION DATE

June 2007

### APPLICATION SITUATION

Waste drain on 2nd floor above production packing area.

### PROBLEM

Leak around drain allowed waste product into the sanitary production packaging floor below.

### PRODUCTS

Belzona® 4111 (Magma Quartz)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

Only a small amount of product used to solve a health hazard and to meet American Baking Association standard of cleanliness. This client has a long history of successful Belzona applications.

### PICTURES

1. Unsanitary, leaking drain
2. Surface prepared
3. Belzona® 4111 installed
4. Drain cover installed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve