

## BELZONA REPAIRS RUBBER LINED BRINE TANK

### CUSTOMER

Paper Mill, Alabama

### APPLICATION DATE

February 2008

### APPLICATION SITUATION

Rubber lined brine tank in ower house of paper mill

### PROBLEM

Rubber lining had been damaged locally. It was too costly to get specialist tank repair company to come and make repair.

### PRODUCTS

Belzona® 2111 (D&A Hi-Build Elastomer)

### SUBSTRATE

Steel and Rubber

### APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflet TCC-3.

### BELZONA FACTS

Would have cost over \$2500 for specialist tank company to come make the repair. Used one unit of Conditioner and one unit of Belzona® 2111. Repair was made one day and tank was put back in surface the next day.

### PICTURES

1. Opening to the tank
2. Exposed metal where repair to be made
3. Conditioner applied after grinding
4. Repair completed with Belzona® 2111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve