

NASA GOES WITH BELZONA

CUSTOMER

NASA, Alabama USA

APPLICATION DATE

2003

APPLICATION SITUATION

Machine shop floor was uneven.

PROBLEM

Old coating and repair materials were spalling and causing uneven areas of the floor. Fork trucks and equipment being moved across it was being damaged.

PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. A screed box was used to apply 1/4 inch of Belzona® 4131. After the floor was leveled out Belzona® 5231 was applied in two coats.

BELZONA FACTS

Old coating had failed within 1 year. Belzona has been down 3 years without any issues providing an aesthetic non-slip surface.

PICTURES

1. Overall view of the floor after preparation by Blastrack
2. Screed box laying out the Belzona® 4131
3. Smoothing out the Belzona® 4131
4. Final coats of Belzona® 5231



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve