

BELZONA GETS TRACTOR BACK ON TRACKS

CUSTOMER

Agricultural Equipment Suppliers, UK

APPLICATION DATE

March 2008

APPLICATION SITUATION

Rubber tractor tracks

PROBLEM

Abrasion of rubber on inside surface of tracks

PRODUCTS

Belzona® 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Rubber / steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

Belzona is the approved repair method by Manufacturer. Whole repair will cost £250. New tracks cost £5500.

PICTURES

1. General view of track before repair
2. Close up of damaged area
3. After repair
4. Back on track

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve