

UNIVERSITY STUDIES BELZONA FLOOR SOLUTION

CUSTOMER

University, St Louis, Missouri U.S.A.

APPLICATION DATE

Spring 2008

APPLICATION SITUATION

Floor areas in service areas/boiler room.

PROBLEM

Floor caused trip hazards for employees and previous coatings required annual refurbishment.

PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflets FPA-1 & -3.

BELZONA FACTS

This had been a yearly repair and customer was looking for long term solution.

PICTURES

1. Floor before repairs and coating
2. Close up of floor problems
3. Holes in floor repaired with Belzona® 4111
4. Floor after coating with Belzona® 5231



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve