Know-How*in Action*

Vol.XXIII No.83

BELZONA ROOF SYSTEM PROVIDES ADDED BENEFITS

CUSTOMER
Chocolate manufacturer, Kansas City

APPLICATION DATE
March 2008

APPLICATION SITUATION
Roof over a kitchen and retail shop.

PROBLEM
Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.

PRODUCTS
Belzona® 3111 (Flexible Membrane)
Belzona® 4111 (Magma Quartz)

SUBSTRATE
Rolled roofing, mastic, brick and clay tile

APPLICATION METHOD
Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, -8, -10 and -11.

BELZONA FACTS
The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona® 3111 was applied. Since the completion of the project, this operation has not had to pursue an HVAC upgrade and the chocolates are once again flawlessly beautiful and delicious.

PICTURES
1. Storefront of world renowned chocolate maker
2. View of the roof prior to remediation
3. Application in progress
4. Completed application

1.

2.

3.

4.

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2011