

## TANK BASE SEALING WITH BELZONA

### CUSTOMER

Power Station, Portland, Philadelphia USA

### APPLICATION DATE

August 2003

### APPLICATION SITUATION

Oil storage tank.

### PROBLEM

Corrosion at chime angle and water getting under the tank bottom

### PRODUCTS

Belzona® 3111 (Flexible Membrane)

### SUBSTRATE

Steel and concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

### BELZONA FACTS

This is a well proven system for reducing corrosion around tank base where moisture is penetrating beneath tank base.

### PICTURES

1. View of the tank
2. Chime angle before application
3. & 4. Finished application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve