

TIRE REPAIR WITH BELZONA ELASTOMER

CUSTOMER

Processing plant, Bulgaria

APPLICATION DATE

December 2003

APPLICATION SITUATION

Rear tire of front end loader.

PROBLEM

A piece of metal penetrated the sidewall.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The client insisted on repairing this tire based on his good experience with Belzona solutions and the alternative expensive replacement. The tire was in service nearly one year following the repair.

PICTURES

1. Size of the tire clearly evident
2. The metal alongside and the damage it caused
3. Prepared and conditioned area
4. Finished Elastomer repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve