

## BELZONA SEALS HYDRAULIC LEAK

### CUSTOMER

Manufacturer of Stone and Marble Products

### APPLICATION DATE

August, 2009

### APPLICATION SITUATION

Hydraulic system of press for stone products

### PROBLEM

Hydraulic pipe had started to leak causing the fluid to drip onto the electrical circuit panel, causing a shutdown.

### PRODUCTS

Belzona® 1111 (Super Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. A wrap using the Belzona® 1111 with Belzona® 9341 (Reinforcement Tape) was used to encapsulate the leaking weld.

### BELZONA FACTS

Repair was able to stop the leak and get the operating press back up and running in a short amount of time minimizing disruption to production.

### PICTURES

1. Leaking weld joint
2. Surface preparation
3. Completed repair

1.



2.



3.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve