

## TRANSFORMER LEAK SEALED WITH BELZONA

### CUSTOMER

Power Plant, Lithuania

### APPLICATION DATE

September 2009

### APPLICATION SITUATION

Transformer was leaking oil through the flanges.

### PROBLEM

Maintenance department had tried different techniques and products but none of these applications were successful. They did not want to take transformer out of service.

### PRODUCTS

Belzona 1161 (Super UW-Metal)

### SUBSTRATE

Carbon Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

### BELZONA FACTS

Plant has tried other products but none of them gave satisfactory results. Belzona solution provided means of sealing the leaks without interruption to supplies.

### PICTURES

1. Paint and other contamination removed
2. Substrate roughened
3. Belzona 1161 and Reinforcement Tape applied
4. Second layer of Belzona 1161



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve