

BELZONA FIXES DRAINAGE PROBLEM

CUSTOMER

Office Building, Ontario Canada

APPLICATION DATE

May, 2009

APPLICATION SITUATION

Parking garage storm drain

PROBLEM

Previously installed coating system had failed and was stopping the water or anything else from draining out.

PRODUCTS

Belzona® 5811 (Immersion Grade)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The failed coating was ground out to expose clean concrete before application of the Belzona® 5811.

BELZONA FACTS

Customer was very happy with the solution. They now have a drain that gets rid of the water and their worries.

PICTURES

1. Water and trash not able to escape
2. Removing the old system
3. Grinding back to white concrete
4. Belzona® 5811 applied



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve