

BELZONA SOLVES KITCHEN TRIP HAZARD

CUSTOMER

Hospital, Charlotte, North Carolina USA

APPLICATION DATE

January, 2009

APPLICATION SITUATION

Transition between a rubber floor and a tiled floor.

PROBLEM

There is a big transition which was causing a trip hazard as well as limiting cart traffic.

PRODUCTS

Belzona® 4111 (Magma Quartz)

SUBSTRATE

Concrete, rubber and tile

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -5. The rubber floor was cut out so a slope could be made from the edge of the rubber floor to the tile so that a smooth transition could be created.

BELZONA FACTS

Belzona application offered a long term solution with minimum downtime, quick turnaround, and no VOCs to taint the working environment.

PICTURES

1. Coin shows the transition step
2. Exposed concrete after rubber floor removal.
3. Applying the Belzona 4111
4. The finished job



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve