

BELZONA REPAIRS CASING OF CEMENT BALL MILL

CUSTOMER

Cement plant, Egypt

APPLICATION DATE

November 2008

APPLICATION SITUATION

Ball mill used to grind limestone in cement production.

PROBLEM

Wear on the casing needed to be rebuilt before the bolting of the new wear plates.

PRODUCTS

Belzona® 1121 (Super XL-metal)

SUBSTRATE

Cast iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-7.

BELZONA FACTS

Belzona successfully solved this problem in a moderate price.

PICTURES

1. General view of the mill.
2. Wear on the shell after dismantling the plates.
3. Application of Belzona® 1121.
4. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve