

BELZONA REPAIRS LIVE LEAK ON TRANSFORMER

CUSTOMER

Electricity Distribution Company, UK

APPLICATION DATE

2007

APPLICATION SITUATION

Pipework on oil filled transformer.

PROBLEM

Oil leak causing environmental contamination.

PRODUCTS

Belzona 1161 (Super UW-Metal)

Belzona 1291 (ES-Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried in accordance with Belzona Know-How System leaflet VPF-11a. Belzona 1291 used to firstly seal the live leak. The pipework was then encapsulated to prevent further leakage.

BELZONA FACTS

The costly need to drain down the oil to effect a repair (£8,000) was eradicated, the Belzona repair was carried out in less than 2 hours.

PICTURES

1. Leak area
2. Leak stopped with Belzona 1291
3. Application completed with Belzona 1161

1.



2.



3.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA
Repair • Protect • Improve