

## BELZONA REPAIRED STEPS IN GREAT CONDITION AFTER 5 YEARS

### CUSTOMER

Local City Council, N.East England

### APPLICATION DATE

May 2005

### APPLICATION SITUATION

Promenade steps on coast needing repairs.

### PROBLEM

Due to the steps being on the sea front, over a number of years they had deteriorated where the nosings were damaged and in dangerous condition.

### PRODUCTS

Belzona® 4131 (Magma Screed)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

The customer had previously carried out localised repairs using alternative concrete repair materials. These products, however, were not effective due to poor adhesion and the nature of the coastal environment. An inspection of the Belzona repairs was carried out after 5 years and there is no signs of deterioration or damage to the step nosings.

### PICTURES

1. Steps before repair
2. Immediately after repair
3. Steps after 5 years use
4. Close up showing no deterioration after 5 years.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve