Know-Howin Action

BELZONA PROVIDES SAFE WELCOME

CUSTOMER

Manufacturer, Slovakia

APPLICATION DATE

2008

APPLICATION SITUATION

Main entrance into companies offices.

PROBLEM

During rain or snow people have slip problems on the ramp into the offices.

PRODUCTS

Belzona® 1321 (Ceramic S Metal)

SUBSTRATE

Floor tiles

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 1321 was applied by brush in conjunction with Belzona® 9211 (Supergrip Aggregate). Templates were used to create logo.

BELZONA FACTS

Customer achieved a quick, distinctive and attractive solution. The message reads "welcome to our firm Slovcem".

PICTURES

- 1. Ramp entrance
- 2. Templates being placed
- 3. Completed application







વ

For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com



BELZONA® Repair • Protect • Improve