

## EXTERNAL TANK CORROSION PROTECTION WITH BELZONA

### CUSTOMER

Fuel distribution company, Tamaulipas, Mexico

### APPLICATION DATE

August 2000

### APPLICATION SITUATION

Oil storage tank

### PROBLEM

Tank walls were suffering from external corrosion

### PRODUCTS

Belzona® 6111 (Liquid Anode)

Belzona® 5111 (Ceramic Cladding)

### SUBSTRATE

Carbon Steel

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

### BELZONA FACTS

10 years after the application, the inspection showed the Belzona product was in perfect condition. The Belzona application saved the customer an estimated US\$ 39,500 through reduced maintenance costs.

### PICTURES

1. Surface preparation
2. Applying Belzona® 6111
3. Application completed
4. Tank ten years after application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve