

BELZONA REBUILDS BAKERY FLOOR

CUSTOMER

Bakery, Northern Ireland

APPLICATION DATE

August 2009

APPLICATION SITUATION

Floor area around dough making machine.

PROBLEM

Oils, flour and cleaning water were going under the dough mixing machine. falls needed to be created to enhance drainage and ease of cleaning in this hygiene area.

PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & 6. A flexible seal using Belzona® 2221 was included to absorb the machines vibrations and to prevent foodstuffs from going under the machine.

BELZONA FACTS

The machine was fully operational again next afternoon, preventing any trouble with production. It has led to a number of repeat floor repair works, all using Belzona® 4131 to provide a clean, safe working surface.

PICTURES

1. Floor problem area
2. Floor area after cleaning and abrasion
3. Belzona Conditioner being applied
4. Floor area screeded with Belzona® 4131



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve