

BELZONA UPGRADE TO FLOOR IN CHOCOLATE FACTORY

CUSTOMER

Chocolate manufacturer, Derbyshire, UK

APPLICATION DATE

December 2009

APPLICATION SITUATION

Floor in canteen wash area.

PROBLEM

The existing coating had begun to deteriorate and sections of the main walk area had been removed exposing the concrete substrate beneath. This was not only unsightly; it also represented a health risk as staff were unable to clean the floor area adequately as food particles become trapped in the surface. The area also presented a considerable slip risk.

PRODUCTS

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

The remainder of the original floor coating was uplifted and the whole concrete floor area Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3.

BELZONA FACTS

The clients requirements and expectations have been met in full and they are very pleased with the results. the floor provides a hygienic surface that cannot harbour bacteria and also provides a slip resistant surface for the staff.

PICTURES

1. & 2. Floor Areas to be Repaired
3. & 4. Completed Floor Application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve