

BELZONA REPAIRS AND PROTECTS PUMP CASING

CUSTOMER

BC, Canada

APPLICATION DATE

July 2002

APPLICATION SITUATION

Pump Casing

PROBLEM

Pump casing was showing signs of degradation. This was from possible contamination during casting process.

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalglide)

SUBSTRATE

Cast Iron

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-3, CEP-5.

BELZONA FACTS

A Belzona repair allowed the damaged areas to be quickly rebuilt and the casing protected from further bi-metallic erosion.

PICTURES

1. View of casing showing damaged areas requiring rebuilding.
2. Application of 1st coat of Belzona 1341 in progress
3. Completed application.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve