

BELZONA REPLACES FAILED TANK BASE SEAL

CUSTOMER

Chemical plant, UK

APPLICATION DATE

November 2004

APPLICATION SITUATION

Base of chemical storage tank

PROBLEM

Original seal had cracked and allowed moisture to penetrate beneath tank base. Problem exacerbated by poor water shed leading to external corrosion.

PRODUCTS

Belzona® 4131 (Magma-Screed)

Belzona® 3111 (Flexible Membrane System)

SUBSTRATE

Steel & concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3 and TCC-9.

BELZONA FACTS

Traditional sealing materials had failed due to lack of flexibility. Improved water shed created by applying fillet of Belzona® 4131. Belzona® 3111 has a proven track record in waterproofing tank bases.

PICTURES

1. Close up showing failure of original seal.
2. Fillet of Belzona® 4131 applied
3. Application of Belzona® 3111 System underway.
4. Application completed.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve