

## BELZONA REFURBISHMENT MAKES FIRE ESCAPE SAFE

### CUSTOMER

Police Station, UK

### APPLICATION DATE

November 2010

### APPLICATION SITUATION

Fire escape stairs

### PROBLEM

Regular foot traffic and weathering caused the steps of this fire escape to become damaged and worn and had made it a potential slip hazard.

### PRODUCTS

Belzona® 4411 (Granogrip)

Belzona® 5111 (Ceramic Cladding)

Belzona® 6111 (Liquid Anode)

### SUBSTRATE

Steel

### APPLICATION METHOD



Application was carried out in accordance with a modified Belzona Know-How System Leaflet FPA-8. Belzona® 4411 (Granogrip) was applied to the steps with aggregate incorporated in grey and yellow. Belzona® 5111/6111 system applied to the hand rails. Belzona® 1111 was used to smooth out corroded steelwork.

### BELZONA FACTS

This solution was chosen as it is a long life and cost effective repair. The customer was extremely pleased with the aesthetic appearance of the application. The Belzona Grip system provides both positive grip and improved visibility to step nosings.

### PICTURES

1. & 2. Original condition of the entrance steps
3. & 4. The finished application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve