

BELZONA SEALS PLANT ROOM FLOOR

CUSTOMER

Hospital, UK

APPLICATION DATE

May 2009

APPLICATION SITUATION

Boiler plant room of a hospital

PROBLEM

Water was leaking through the floor to the operating theatres below.

PRODUCTS

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The floor was first diamond ground and then two coats of Belzona® 5231 applied.

BELZONA FACTS

The whole application was carried out over one weekend. The low odour, solvent free Belzona® 5231 did not impact on normal operating of the hospital.

PICTURES

1. Damaged floor
2. Belzona® 5231 application starting
3. & 4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

