

BELZONA REPAIRS COLOUR MATCH SPALLED LINTELS

CUSTOMER

Local Education Authority, UK

APPLICATION DATE

September 2009

APPLICATION SITUATION

Concrete lintels.

PROBLEM

Spalled concrete due to rebar corrosion.

PRODUCTS

Belzona® 4141 (Magma Build)

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet WPA-4. Belzona® 4141 was colour matched to existing concrete using Iron Oxide pigments.

BELZONA FACTS

Repair was carried out quickly without need for scaffolding or permanent shuttering. Ability to colour match the repair ensured aesthetic acceptability.

PICTURES

1. Spalled concrete.
2. Application in process using straight edge to form neat corner.
3. Completing the application.
4. Completed application. Note excellent colour match.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve