

BELZONA REPAIRS ROOF AT PRESTIGIOUS UNIVERSITY

CUSTOMER

University Library, UK

APPLICATION DATE

Summer 2010

APPLICATION SITUATION

The mineral felt roof and gutters were in poor condition with various areas leaking directly into the reading room below where many historic books are stored and read daily by students.

PROBLEM

Strict requirements needed to be adhered to when repairing this roof. Application had to be carried out with library in full use by students.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Mineral felt with chippings

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, 6 & 8.

BELZONA FACTS

The University had experienced problems before with students complaining about the smell and feeling ill due to competitors solvent-based roofing products being used on other University buildings. Belzona® 3111 fully reinforced system was applied without disruption to the daily use of the library reading rooms below.

PICTURES

1. Damaged gutter prior to the application
2. Gutter coated with Belzona® 3111
3. Leaking roof area
4. Roof coated with Belzona® 3111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve