

BELZONA UPGRADES FLOOR IN FOOD PREPARATION AREA

CUSTOMER

School, UK

APPLICATION DATE

October 2010

APPLICATION SITUATION

Floor in food preparation area.

PROBLEM

The floor was slippery creating a health and safety issue. In addition the concrete was being damaged around drains.

PRODUCTS

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating before applying the 2 coat Belzona® 5231 system by roller.

BELZONA FACTS

The school chose the Belzona solution for their floor problems as they wanted a seamless, hard-wearing and long lasting coating. They had a maximum of 4 days to complete the repair and Belzona were the only company able to accommodate this.

PICTURES

1. & 2. Floor Problem Area
3. & 4. Completed Floor Application


1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve