

## BELZONA SEALS TANK AT CABLE MANUFACTURER

### CUSTOMER

Cable manufacturer, US

### APPLICATION DATE

December 2010

### APPLICATION SITUATION

Welded seam, oil storage tank.

### PROBLEM

Interior bottom cone of tank was leaking resulting in safety issues. severe corrosion pitting present particularly at the welded seams.

### PRODUCTS

Belzona® 1111 (Super Metal)

Belzona® 5811 (Immersion Grade)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-1 & 5. Welded seams and pits were sealed with Belzona® 1111. Two coats of Belzona® 5811 were applied.

### BELZONA FACTS

Approximately \$2,000 of Belzona material was used on a \$32,000 tank extending the life and function of the tank. Belzona® 5811 provides long term corrosion protection in immersed conditions.

### PICTURES

1. Exterior of tank
2. Pitted bottom after cleaning and blasting
3. Belzona® 1111 seals welds and holes
4. First coat of Beige® 5811 applied



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve