

## BELZONA RESTORES HYGEINE IN BOTTLING ROOM

### CUSTOMER

Bottled Water Manufacturer, Perthshire, UK

### APPLICATION DATE

September 2010

### APPLICATION SITUATION

Tiled floor in bottling room.

### PROBLEM

There were several cracked and broken tiles. This created a potential hygiene problem and required rectifying to remove traps for bacteria and to aid cleaning.

### PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 5231 (S G Laminate)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & 3. Belzona® 4131 was used to replace loose tiles and create a uniform surface prior to application of the Belzona® 5231.

### BELZONA FACTS

The Belzona System creates a level, seamless surface that is hygienic in this critical area. The low VOC, low odour of the system was a further benefit in this bottling plant.

### PICTURES

1. Damaged tiles being repaired with Belzona® 4131
2. Floor levelled with Belzona® 4131
3. Light grey Belzona® 5231 being applied
4. Completed floor coating



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>