

## BELZONA PROTECTS KORT NOZZLES

### CUSTOMER

Tug boat operator, Egypt

### APPLICATION DATE

May 2009

### APPLICATION SITUATION

Pair of kort nozzles on tug boat

### PROBLEM

The Kort nozzles were suffering badly from erosion corrosion.

### PRODUCTS

Belzona® 1321 (Ceramic S-Metal)

### SUBSTRATE

Mild Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

### BELZONA FACTS

Belzona successfully solved this problem and provided long term protection to the nozzles from excessive erosion-corrosion.

### PICTURES

1. The boat in dry dock
2. Grit blasting the nozzles
3. Applying of Belzona® 1321
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve