

BELZONA RESTORES SAFETY TO FIRE ESCAPE STAIRWAY

CUSTOMER

Water Supplier, UK

APPLICATION DATE

April 2011

APPLICATION SITUATION

Smooth concrete fire escape stairway

PROBLEM

The concrete steps had worn and the current safety grip system had become almost none existent due to heavy foot traffic and weathering. A member of staff had slipped down the steps and injured themselves so solution to this serious slip hazard required.

PRODUCTS

Belzona® 4411 (Granogrip)

SUBSTRATE

Concrete

APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4411 in grey was applied to the steps with Belzona® 9221 (Surefoot White Aggregate) incorporated into the main step areas and Belzona 9231 (Surefoot Aggregate) incorporated into the coating on the nosings.

BELZONA FACTS

The client was looking for a quick solution to overcome this safety issue and selected the Belzona solution as Belzona system offered not only a quick but also long term solution. The application was completed within 3 weeks with minimal disruption to employees and is now providing a safe well gripped fire escape.

PICTURES

1. Staircase prior to application
2. Surface prepared ready of application
3. Completed Application
4. Completed Application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

