

BELZONA RESTORES LOCAL BANK

CUSTOMER

Bank, Scotland

APPLICATION DATE

March 2011

APPLICATION SITUATION

Window sills, lintels and the external walls of the bank.

PROBLEM

Age and the effect of weather had caused serious deterioration to the buildings facade.

PRODUCTS

Belzona® 4141 (Magma-Build)

Belzona® 5151 (Hi-Build Cladding)

SUBSTRATE

Stone

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets WPA-1 and WPA-4. The defective external wall coatings were removed. Some of the broken profiles around the windows and the lintel above the front door were repaired with Belzona® 4141. Belzona® 5151 was then applied to the stonework to protect the surface from further damage.

BELZONA FACTS

The poor appearance of the bank led to the village being rejected for a Civic Trust award. This led to pressure on the bank to improve its external facade. The Belzona solution was chosen for its speed in carrying out the upgrade and the self-cleaning properties of the Belzona® 5151 will ensure the buildings appearance will be maintained for many years to come.

PICTURES

1. Fascia of the building prior to application
2. Damaged Column
3. General view of the completed application
4. The refurbished bank entrance



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve