

## SCOOP TRAM WITH DAMAGED PIN BEARING BACK IN SERVICE WITH BELZONA AFTER ONE DAY

### CUSTOMER

Salt mine, Germany

### APPLICATION DATE

November 2009

### APPLICATION SITUATION

Scoop tram operating in salt mine.

### PROBLEM

The severe corrosive and abrasive service conditions had led to metal loss on the articulated joint bearing pin, resulting in a relatively short life of the component.

### PRODUCTS

Belzona® 1821 (Fluid Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

### BELZONA FACTS

Dismantling the pin housing for replacement would have been very time consuming and costly as the entire backing plate would have had to be detached. The Belzona forming technique not only allowed for the repairs to be completed in-situ after just one day but also significantly extended the life expectancy of the scoop tram bearing pin.

### PICTURES

1. Scoop tram before application
2. Injection of the Belzona material
3. Completed application
4. After reassembly of the bearing

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

**BELZONA®**  
Repair • Protect • Improve