

BELZONA STOPS FLOOR DRAIN LEAKS

CUSTOMER

Machinery manufacturer, Slovakia

APPLICATION DATE

2008

APPLICATION SITUATION

Drain in kitchen floor.

PROBLEM

Leakage from the floor drains was problem from the start. Connection between steel and tiles was faulty. Result was the leakage to the next floor.

PRODUCTS

Belzona® 4111 (Magma Quartz)

SUBSTRATE

stainless steel, concrete, ceramic tiles

APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

Customer had tried several alternatives to repair the drain but none worked. Repair with Belzona® 4111 ensured necessary water tightness due to excellent adhesion to different substrates and non-shrink properties.

PICTURES

1. Situation before repair
2. Situation at the floor below
3. Surface preparation being carried out
4. Belzona® 4111 in place creating a watertight seal



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve