

BELZONA WATERPROOFS SUNROOM ROOF

CUSTOMER

Residential Roof in Ontario

APPLICATION DATE

June, 2009

APPLICATION SITUATION

A poor roofing job left customer with a leaking sunroom.

PROBLEM

The roof and flashing on this customers sunroom was allowing water to enter and damage walls and belongings.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Asphalt

APPLICATION METHOD


Using modified Belzona Know-How Systems Leaflet RPA-1, a fully reinforced Belzona® 3111 System was applied.

BELZONA FACTS

When the roof began leaking, the customer looked to the contractor to honor their warranty, but discovered that the contractor was out of business. Belzona provided the solution the customer was looking for and now dry walls and floors keep this customer a Belzona believer.

PICTURES

1. Applying Belzona® 3911 (Conditioner)
2. Initial application of Belzona® 3111 incorporating Reinforcing sheet in 1st Coat
3. & 4 Finished application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve