

BELZONA SEALS LARGE BUND AREA

CUSTOMER

Metals manufacturer, Herefordshire, UK

APPLICATION DATE

November 2012

APPLICATION SITUATION

Chemical bund on large manufacturing site

PROBLEM

The site regularly test for leaks due to high standards in health and safety and environmental issues. This test showed the bund's brickwork to be leaking from several areas.

PRODUCTS

Belzona® 5811 (Immersion Grade)

Belzona® 4131 (Magma Screed)

SUBSTRATE

Brick

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-9 and TCC-15. The application took place during the planned two week shutdown, causing no disruption to production.

BELZONA FACTS

Belzona has been used on this site to provide solutions in a number of different areas. They now look to Belzona to provide alternative solutions when traditional repairs are inadequate.

PICTURES

1. Before application
2. Creation of fillets at wall/floor joint with Belzona 4131
3. Application of first coat Belzona 5811
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve