

BELZONA UPGRADES SAFETY AND APPEARANCE OF SCHOOL ENTRANCE

CUSTOMER

Secondary School, Port Talbort, South Wales

APPLICATION DATE

May 2012

APPLICATION SITUATION

Steps leading to school main entrance

PROBLEM

Step nosings had become damaged and overall very dirty. The school wanted the main entrance upgrading and wanted to ensure the steps were safe for its staff, pupils and visitors.

PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 5231 (SG Lamine)

Belzona® 4411 (Granogrip)

SUBSTRATE

Concrete

APPLICATION METHOD




Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-8. The concrete step nosings were repaired using Belzona® 4111 before coating with Belzona® 5231. Finally a Belzona® 4411 grip system was applied to step nosings.

BELZONA FACTS

The application was completed by Belzona Technosol Limited to a very high standard which was confirmed by the client. Not only has appearance been upgraded but the high visibility, non-slip system on the step nosings provides improved safety by reducing risk of falls.

PICTURES

1. Deteriorating steps at the entrance to the school
2. Repair to steps using Belzona® 4111
3. Application of Belzona® 5231 overall
4. Complete repair with Belzona® 4411 grip system applied to the step nosings.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve