Know-How*in Action*

Vol.XXVII No.70

BELZONA SOLVES FINLOCK GUTTER ISSUES

CUSTOMER
Housing Association, Herefordshire, UK

APPLICATION DATE
March 2013

APPLICATION SITUATION
Rows of Finlock Gutters on Housing Association Properties.

PROBLEM
Finlock gutters had begun to leak into the properties.

PRODUCTS
Belzona® 3131 (WG Membrane)
Belzona® 4141 (Magma Build)

SUBSTRATE
Concrete

APPLICATION METHOD
Application was carried out in accordance with Belzona Know-How System Leaflets RPA-6 and RPA-11. Any damaged areas of concrete were repaired using Belzona® 4141 followed by complete coating with the reinforced Belzona® 3131 system.

BELZONA FACTS
The housing association had tried a number of different solutions including metal liners, felt and another liquid applied product. Belzona has a long successful history of repairing and sealing finlock gutters.

PICTURES
1. Before Application
2. Removal of existing liners
3. Application in progress
4. Completed Application.

1.

2.

3.

4.

For more examples of *Belzona Know-How In Action*, please visit http://khia.belzona.com

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2013