

## BELZONA SEALS LEAKING MUSIC ROOM ROOF

### CUSTOMER

Prestigious boarding school, Somerset, England

### APPLICATION DATE

August, 2012

### APPLICATION SITUATION

Roof over the music room at a prestigious private school

### PROBLEM

Breakdown of the old bituminous substrate had allowed multiple area's of water ingress causing damage to the fabric of the building & creating health and safety issues. Due to it's location adjoining a listed school building a hot applied system was not acceptable.

### PRODUCTS

Belzona 3131 (WG Membrane)

### SUBSTRATE

Bitumen

### APPLICATION METHOD

The application was carried out in strict accordance with Belzona System leaflet RPA-1.

### BELZONA FACTS

The Belzona solution being cold curing, combined with its ease of application and ability to seal the various roof details met the clients requirements.

### PICTURES

1. Close up of previous repairs which had failed
2. Preparation of the roof by removing loose chippings
3. First coat of Belzona 3131 being applied with reinforcement sheet
4. Completed application several months later



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>