

## BALCONIES WATERPROOFED WITH BELZONA

### CUSTOMER

Boutique Hotel, London

### APPLICATION DATE

June 2013

### APPLICATION SITUATION

Balconies on Victorian era hotel

### PROBLEM

The aging balconies had numerous fine cracks and the hotel had been suffering from water penetration issues. With high occupancy rates a quick turnaround was essential.

### PRODUCTS

Belzona® 5811 (Immersion Grade)

### SUBSTRATE

Concrete

### APPLICATION METHOD




Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-15. The Belzona 5811 was applied using brushes and squeegees.

### BELZONA FACTS

Due to the products solvent free properties the contractor was able to complete the application very quickly and without any disruption to the hotel guests. The standard grey colour also complemented the existing colour scheme on the exterior of the hotel. As the balconies don't get used there was no need for a grip system.

### PICTURES

1. Unprotected balconies
2. Contractor carrying out application
3. & 4. Completed work



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve