

BELZONA GIVES OLD PROPERTY NEW LEASE OF LIFE

CUSTOMER

Farm house, Worcestershire, UK

APPLICATION DATE

June 2013

APPLICATION SITUATION

Old farm house walls.

PROBLEM

Failure of the existing paint was allowing damp to penetrate into the walls leading to further deterioration. Client needed system to protect walls and approve appearance.

PRODUCTS

Belzona® 5151 (High Build Cladding)

SUBSTRATE

Brick

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1. A mechanical wire brush was used over the entire surface to remove loose material. After treating with fungicidal wash the Belzona® 5151 system was applied.

BELZONA FACTS

Due to the contractor using Belzona products on a number of very successful applications within the social housing sector they were able to demonstrate the effectiveness of the Belzona® 5151 system to the client.

PICTURES

1. Surface Preparation
2. Application of Belzona® 3911 (PSC Conditioner)
3. Completed Belzona® 5151 Application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

