

BELZONA PROTECTS ROTARY REACTOR (LEACHING TANK)

CUSTOMER

Mining Company, Indonesia

APPLICATION DATE

November, 2006

APPLICATION SITUATION

Rotary Reactor (Leaching Tank)

PROBLEM

To protect new rotary reactor (Leaching Tank) from chemical attack while processing/operating.

PRODUCTS

Belzona 1392 (Ceramic HT2)

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet TCC-5.

BELZONA FACTS

Offered protection at high temperature.

PICTURES

1. Internal wall, prior to surface preparation
2. Degreasing with Belzona 9111
3. Application of Belzona 1392
4. Complete application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve