

BELZONA REPAIRS SCORED HYDRAULIC RAM

CUSTOMER

BC, Canada

APPLICATION DATE

August 1996

APPLICATION SITUATION

Damaged hydraulic ram

PROBLEM

Hydraulic rams had been subjected to sever mechanical damage around the seal area, rendering them ineffective. This was the only heavy duty lifter used for loading on site. New ram was not immediately available.

PRODUCTS

Belzona 1221 (Super E-Metal)

SUBSTRATE

Chromed steel rod

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet MPT-3

BELZONA FACTS

Using Belzona 1221, an emergency repair material, allowed the rams to be rebuilt on site in a matter of hours.

PICTURES

1. View of damaged ram
2. Damaged areas "V" out
3. Rebuilt with Belzona 1221
4. Completed repair.

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve