

BELZONA REPAIRS RUBBER LINED SLURRY PUMP

CUSTOMER

BC, Canada

APPLICATION DATE

1990

APPLICATION SITUATION

Rubber lining on a slurry pump

PROBLEM

A hole had worn into the rubber lining in a number of areas from the coal slurry and had started to erode the metal casing.

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Steel/ Rubber

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-11

BELZONA FACTS

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

PICTURES

1. Preparation of the damaged areas in progress
2. Preparation completed
3. Rubber liner rebuilt



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA[®]
Repair • Protect • Improve