

BELZONA REBUILDS WORN CAT D9 SPLINE SHAFT ASSEMBLY

CUSTOMER

BC, Canada

APPLICATION DATE

N/A

APPLICATION SITUATION

Worn spline shaft

PROBLEM

The main drive spline on D-9 cat had worn loose over many years of service.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet MPT-5

BELZONA FACTS

With applications of Belzona, the option to disassemble can be done when required

PICTURES

1. View of worn spline shaft assembly
2. Belzona 1111 Super Metal applied to worn splines
3. Components reassembled
4. The main framework that the Spline assembly is being bolted to



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve