

BELZONA EXTENDS THE LIFE OF DAMAGED TIRE

CUSTOMER

BC, Canada

APPLICATION DATE

1999

APPLICATION SITUATION

Repair of the side wall of a tire

PROBLEM

The side wall of a tire, close to the rim, had been cut by a stray piece of metal

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1. Surface around damaged area cleaned of loose road debris and roughen with a steel wire brush. Belzona 2911 (Elastomer QD Conditioner) was applied prior to Belzona 2211 to ensure proper adhesion.

BELZONA FACTS

Repairing cuts like this as soon as possible after the event ensures that no further degradation of the tire will take place resulting from water or debris.

PICTURES

1. Vehicle with damaged tire
2. Initial preparation underway with the removal of any loose material
3. The surface around the damaged area is prepared with a special roughing tool
4. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve