

BELZONA ELASTOMERS USED TO PROTECT CONVEYOR BELT CLIPS

CUSTOMER

BC, Canada

APPLICATION DATE

1998

APPLICATION SITUATION

Belt clip

PROBLEM

The fine gravel was constantly wearing out a clip joint

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber and steel

APPLICATION METHOD



Application carried out in accordance with Belzona Know-How System Leaflet SHM-1 and SHM-4

BELZONA FACTS

The use of the Belzona procedures enabled the clip joint to be permanently protected and the damaged section of the belt repaired at the same time

PICTURES

1. Preparation of the clip joint and damaged area in progress
2. Preparation completed
3. Area masked off and the prepared area conditioned with Belzona 2911 (QD Conditioner)
4. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve