

BELZONA RESCUES CELL PHONE ANTENNAS

CUSTOMER

Deer Park, WA, USA

APPLICATION DATE

June 2014

APPLICATION SITUATION

Steel mounting plates.

PROBLEM

A series of steel plates with expensive cell phone antennas mounted to them on this water tower were found to be failing. The previous product had dis-bonded and they were no longer attached to the water tower.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Previous material was removed, the surface of the plates were ground clean, and then roughened as well as the sides. The four sides of the plate were also chamfered to produce an additional mechanical bond once the Belzona 1111 had cured. The steel surface of the water tower was also ground to remove the previous material and then prepared with the MBX Bristle Blaster. Belzona 1111 was then mixed, and applied and the plate was remounted in it's original position.

BELZONA FACTS

Belzona 1111 Super Metal was being used on this site for new cell antenna mounts when the failing mounts were discovered. Unnoticed, the failed mounts could have cost the cell phone company tens of thousands of dollars in equipment had they fallen, plus the potential physical danger to anyone in the area below.

PICTURES

1. Failing plate in place
2. Failed plate
3. Application complete
4. View from the ground



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve