

BELZONA STOPS LUBE LEAKS

CUSTOMER

Beaumont, Texas, USA

APPLICATION DATE

April 2014

APPLICATION SITUATION

Concrete wall leaking lube oil

PROBLEM

The customer stored lube oil within a small containment area, when leaks would develop they would by-pass and go under the wall onto the ground outside of the containment area.

PRODUCTS

Belzona 5811 (Immersion Grade)

Belzona 9331 (Reinforcing sheet)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3.

BELZONA FACTS

The customer was using vital manpower and resources having to constantly clean-up the ground outside of the containment area, the Belzona application keeps the lube within the containment for easy clean-up.

PICTURES

1. Before repair
2. During repair
3. Application completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA®
Repair • Protect • Improve