

BELZONA 3411 SOLVES CORROSION ISSUE FOR A CHEMICAL PLANT

CUSTOMER

Chemical Plant, South Louisiana, USA

APPLICATION DATE

June 2014

APPLICATION SITUATION

52" flange on vessel

PROBLEM

Customer has 52" flange on vessel that needs corrosion protection. Other vessels in unit have hefty fiberglass coverings that are difficult to remove and expensive to apply.

PRODUCTS

Belzona 3411 (Flange Encapsulating Membrane)

Belzona 8411 (Conditioner)

Belzona 9311 (Reinforcement sheet)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-11.

BELZONA FACTS

Customer saved several thousand dollars over previous FRP system with easier installation and now can inspect, or if vessel has to be opened, can use a box knife instead of a heat gun or grit blast equipment! Customer had seen Belzona 3411 advertised in Distributor Newsletter and thought it was worth trying this application. The unit was inspected 90 days after the install and it looked as good as it did on day 1.

PICTURES

1. 52" Flange prepared for application, grit blasted
2. First coat of Belzona 3411
3. Second coat of Belzona 3411
4. Final sideview of flange



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

