

SUCCESSFUL RESTORATION OF ROOF IN CENTRAL LONDON WITH BELZONA

CUSTOMER

Finance company, central London

APPLICATION DATE

August 2012

APPLICATION SITUATION

Inverted roof covered in a single-ply membrane.

PROBLEM

Despite the roof appearing to be in good condition, it was found to be leaking in several places.

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Single-ply membrane

APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. The upper level roof was cleaned and prepared before application of a fully reinforced Belzona 3111 system.

BELZONA FACTS

Following a successful roofing application two years earlier, Belzona were approached again by the company to repair and protect the leaking roof. The application was completed quickly and efficiently. The Project Coordinator said, "The contractors who carried out the works did a great job in a professional manner and we experienced no interruptions to business or complaints throughout the entire project. I will definitely be recommending Belzona in any future projects where their system can be used."

PICTURES

1. Surface being conditioned to ensure good adhesion
2. First coat of Belzona 3111 applied
3. Completed application
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA
Repair • Protect • Improve